

Speed Check Services - Results Sheet				Overall % = 42%			
Session#: BUR-2-15		Town/Village: BURY		TotCount = 236			
Date: 01/08/2015 (Sat)		Location: UPWOOD RD @ PEDESTRIAN XING @ 30 LIMIT			Limt: 30 mph		
Times: 1510-1610		(60 Min)	Ops: KS;DM;;				
Direction 1- Towards: Ramsey			Direction 2- Towards: Upwood				
Device #: DM-01		Caller: DM		Scribe: KS		Wx/Road: Fine/Dry	

Dir'n	35-41	42-49	>=50	Totals	Count	Highest	%
1	34	10	0	44	121	47	36
2	45	9	0	54	115	47	47
Totals>	79	19	0	98	236	47 mph	42%

Any Commercial Vehicles Witnessed exceeding the Speed Limit are shown below:

Assessment:

A very high % speeding and at serious speeds across an unmarked (no paint on the road) but notified/signed dangerous pedestrian crossing where an outbound vehicle at 42mph narrowly missed 2 children cycling across the road at this point. Video available on request.

Recommendation:

1. Do something about making this crossing safer - it is an accident waiting to happen.

A N Other

01487 711111

Cambs Roadwatch (incorporating local Speed Check Services)

<http://www.Cambs-Roadwatch.uk> (for further details)