



BOXWORTH – CRW BI-DIRECTIONAL LOGGER RESULTS TO ASSIST VILLAGE WITH WITH SID PLACEMENT©

ELSWORTH RD – 3 Days - Inbound – 4241 vehicles with 85%ile of 36 mph



Elsworth Rd – 3 Days - Outbound – 3258 vehicles with 85%ile of 41.0 mph



SID Results Outbound – 18,837 vehicles over 21 days with 85%ile of 34.2mph

